What is a heat-set insert press and do you need one?

Asked 3D Content Team
Published October 10, 2026 · Last verified October 10, 2026

Abstract. What a heat-set insert press is, the four kinds (printable, kit, drill-press conversion, industrial) with their published specs, and when a hand-held iron is enough.

Keywords: heat-set-inserts, threads-and-fasteners

Table 1. The number

Type	Published example	What guides the iron	Depth stop	Published specs
Printable press (STL files plus hardware)	Stealth Press 1S, Iconic FAB	Linear rail, retractable reel lifts the iron	Not stated	300 mm MGN12H rail; fits generic, TS100 and Pinecil irons
Printable press (STL files plus hardware)	Minimalist Heat Insert Press	Linear rail, hidden spring and belt return	Not stated	LML12B 200 mm rail; built for a TS100 with CNC Kitchen tips
Printable press (STL files plus hardware)	Heat Set Insert Rig, Adafruit	Roller carriage on extrusion, pulley and weight	Not stated	610 mm 2020 extrusion; 60 W iron
Kit press, partly printed	VLMP 2, Vector3D	V-slot wheels on extrusion, adjustable counterbalance	Adjustable stop	Grip printed in ABS or ASA; takes any iron
Press stand with its own iron	Mintion Nutopress Pro	Linear rail slider	Not stated	90 W iron; 6 tips, M2 to M8; 210 mm working height
Drill-press conversion	Printed adapters for the Dremel 220-01 drill stand	The stand's lever and quill	The stand's own	Adapters published for the Hakko FX-888D and Weller 1010NA irons
Industrial thermal insertion machine	SPIROL Model HM (manual)	Built-in press with air-spring force	Micrometer depth stop	Digital temperature control; M2 to M6
Industrial thermal insertion machine	SPIROL Model HP (pneumatic)	Pneumatic ram, regulated force and speed	Micrometer depth adjustment	Timer, temperature lockout; M2 to M8

1 What is a heat-set insert press and do you need one?

A heat-set insert press is a vertical guide that holds a soldering iron square to the part and lowers it on a rail or lever, so inserts go in straight. Some add a depth stop. You need one for batches, deep or large inserts and production work. For a few inserts, a hand-held iron with an insert tip works.

1.1 The number

Specs as published on each design's Printables page, the Adafruit Learning System guide, the West3D and 3DJake product pages, and SPIROL's equipment pages, read 10 October 2026. "Not stated" means the maker's page does not list a depth stop. This table lists examples, not recommendations.

1.2 Why

A press controls up to three things that a hand-held iron leaves to you.

Perpendicularity. The rail or quill keeps the tip on one axis, so the insert cannot tilt as it sinks. Adafruit's guide puts the whole case in one line: the rig "holds a soldering iron vertically and allows you to press down, perfectly straight." By hand, the insert tilts when you push off-center or when the tip drags it sideways on the way out.

Depth. A stop ends the stroke at the same height every time, so inserts finish flush instead of proud or sunk. Most of the hobby designs in the table do not list one. The VLMP 2 lists an adjustable stop, and both SPIROL machines have a micrometer-style one.

Temperature, force and time. On a hobby press these come from the iron and your hand. Industrial machines set them for you. SPIROL says its drivers remove "the dependency on the operator to control the factors of time, temperature and pressure." It adds that "as much as 75% of an Insert's performance is the direct result of how well it was installed."

The common names map onto these types. A **heat-set insert press STL** is a printable design like the first three rows: you download the STL (3D model) files, print the frame and buy the rail, fasteners and iron. A **vertical heat-set insert press** is any of these.

A **heat-set insert drill press** setup clamps the iron into a drill stand that is not running. The printed adapters above replace the Dremel stand's tool holder with an iron clamp.




Figure 1. The rail lets the iron move only straight up and down, and a depth stop, where the press has one, ends every stroke at the same height.

A **heat-set insert jig** usually means something simpler: a printed fixture that holds the part, or a guide that keeps the iron upright, without a moving carriage.

A press does not replace the right tip. CNC Kitchen's insert tips have a centering pin sized to the insert's bore, so the insert sits square on the tip. The tips fit the TS100, TS101 and Pinecil irons, which several printable presses are built to hold. CNC Kitchen's set covers M2, M2.5, M3, M4, M5, M6 and M8.

1.3 When you need one, and when you don't

A press pays off when:

- **You install many inserts.** Adafruit describes its rig as the tool for "a small production run."
- **Inserts are large or deep.** A small tilt over a long insert puts its top well off axis. A vertical stroke holds the axis the whole way down.
- **Inserts must be dead square.** Mating parts that bolt together across several inserts need every thread on the same axis.
- **The work is production.** Industrial machines are built for batches across many assemblies. SPIROL's platen-style Model PH installs up to 12 inserts in one cycle.

A hand-held iron is enough for a handful of inserts in a hobby part. Seat each one with the two-stage method: the iron sinks the insert most of the way, then a flat tool presses it flush. Hackaday's guide finishes by flipping the part onto a flat, heat-resistant plate, which leaves the insert both vertical and flush. Full steps: How do you install heat-set inserts straight without a press?. Hole sizes are in What hole size does an M3 heat-set insert need?.

A press sets inserts the same way a hand iron does, so the usual rules still apply. Set the temperature as in What temperature should the iron be for PLA, PETG and ABS inserts?, and size the hole to the insert.

If you print your own press, print the parts near the iron in a heat-resistant plastic. The Stealth Press 1S guide calls for PETG (glycol-modified PET), or ideally ASA (acrylonitrile styrene acrylate) or ABS (acrylonitrile butadiene styrene), for the arm and iron mount. The VLMP 2 grip must be ABS or ASA.

1.4 How to check it on your own print

1. Print a test plate in your usual material with five holes at the insert maker's hole size.
2. Install five inserts by hand with an insert tip and the two-stage method.
3. Thread a long screw into each insert by hand and sight along it against a square. Note any screw that leans.
4. Check each insert top with a straightedge: flush, proud or sunk.
5. If all five sit square and flush, you do not need a press at your volume. If some lean or sit at different heights even after you slow down and use the flat-tool finish, a press is the fix.

References

[1] Heat Set Insert Rig (Adafruit Learning System). https://learn.adafruit.com/heat-set-rig?view=all. Accessed October 10, 2026.
[2] Stealth Press 1S, heat set insert press (Iconic FAB, Printables). https://www.printables.com/model/1081157-stealth-press-1s-heat-set-insert-press. Accessed October 10, 2026.
[3] Minimalist Heat Insert Press (Printables). https://www.printables.com/model/832084-minimalist-heat-insert-press. Accessed October 10, 2026.
[4] VLMP 2 Heat Set Insert Press by Vector3D (West3D product page). https://west3d.com/en-au/products/vlmp-heat-set-insert-press-by-vector3d. Accessed October 10, 2026.

[5] Mintion Nutopress Pro Heat Insert Press (3DJake product page). https://www.3djake.com/mintion/nutopress-pro-heat-insert-press. Accessed October 10, 2026.
[6] Heat Insert Drill Press, Hakko FX-888D adapter for the Dremel 220-01 (Printables). https://www.printables.com/model/401191-heat-insert-drill-press. Accessed October 10, 2026.
[7] Dremel To Weller Heat Set Insert Press Adapter (Printables). https://www.printables.com/model/288255-dremel-to-weller-heat-set-insert-press-adapter. Accessed October 10, 2026.
[8] SPIROL Threaded Insert Installation Technology. https://www.spirol.com/product/installation-equipment/threaded-insert-installation-technology/. Accessed October 10, 2026.
[9] SPIROL Model HM Manual Heat Insert Driver. https://www.spirol.com/product/installation-equipment/threaded-insert-installation-technology/model-hm/. Accessed October 10, 2026.
[10] SPIROL Model HP Pneumatic Heat Insert Driver. https://www.spirol.com/product/installation-equipment/threaded-insert-installation-technology/model-hp/. Accessed October 10, 2026.
[11] Installation Tips SET compatible with TS100 and TS101 (CNC Kitchen store). https://cnckitchen.store/products/ts100-101-adapter-tips-set-m2-x-m3-m4-m5-m6-1-4-m8-100-lead-and-cadmium-free. Accessed October 10, 2026.
[12] Tips & Tricks for Heat-Set Inserts used in 3D printing, CNC Kitchen. https://www.cnckitchen.com/blog/tipps-amp-tricks-fr-gewindeeinstze-im-3d-druck-3awey. Accessed October 10, 2026.
[13] Threading 3D Printed Parts: How To Use Heat-Set Inserts (Hackaday). https://hackaday.com/2019/02/28/threading-3d-printed-parts-how-to-use-heat-set-inserts/. Accessed October 10, 2026.

Cite as: Asked 3D. “What is a heat-set insert press and do you need one?” October 10, 2026. https://asked3d.com/answers/heat-set-insert-press. Last verified October 10, 2026.